

London Borough of Hammersmith & Fulham



Fire Risk Assessment of:	100-131 Aspen Gardens, Hammersmith, London. W6 9JF.
Author of Assessment:	Nick Hickman - Fire Safety Surveyor.
Quality Assured by:	Claire Norman, Senior Fire Surveyor, LBH&F
Responsible Person:	Richard Shwe
Risk Assessment Valid From:	10/04/2024
Risk Assessment Valid To:	10/04/2026

London Borough of Hammersmith & Fulham

Building Features

Approximate Square Area of the Building:	500m ²
Number of Dwellings:	32
Number of Internal Communal Stairs:	2
Number of External Escape Stairs:	0
Number of Final Exits:	2
Number of Stair Lifts:	
Number of Storeys	6

Uninhabited Roof Void?	
Basement Present?	
Gas Installed to Building?	yes
Solar Panels Installed on Building?	no

Number of Occupants:	32-65.
----------------------	--------

Current Evacuation Policy:	Stay Put Procedure
Recommended Evacuation Policy:	Stay Put Procedure

Last LFB Inspection:	
----------------------	--

London Borough of Hammersmith & Fulham

Survey Findings:

<p>Building Construction & Layout:</p>	<p>6-storey purpose-built block of flats. Concrete and brick construction, with mix of flat and tiled pitched roofs, with the sections at the end being mansard style containing a flat each. Two staircases interconnected by an open deck balcony on storeys 1-5. One lift serving ground floor to fourth floor. Dry riser inlets located by both entrances. Two bin chute rooms with hoppers located on floors 1-4. S.I.B. located in entrance with the lift. Lift motor rooms accessed via secure staircase from the open deck on the 5th floor. The lift serves all floors other than the 6th storey. Direct access flats (numbers 100-105) on the ground level. Private outboard balconies at the rear. A small parking area shared with the two other blocks that make up the estate (thee buildings have their own FRAs). Built circa 1940s.</p>
<p>Executive Summary</p>	<p>The survey found the communal areas to be well presented with no concerns regarding obstructed escape routes or excessive combustible items. FD30S doors installed to all flats.</p> <p>It is LBHF policy not to fit extinguishers to utility rooms.</p> <p>EICR completed - 21/03/21. Dry Riser service date - to be confirmed. Emergency Lighting service date - to be confirmed. Lightning Protection service date - To be conformed.</p> <p>A number of areas for improvement were identified during the survey and these have been raised in this report. To bring the building to a high standard of fire safety, and support a 'Stay Put' policy, the following actions have been recommended:</p> <p>Repair of the broken arm on the front door closing mechanism on the entrance that has the lift, securing of the notice board by the lift and populating it with required notices, securing of lift signage, setting up of maintenance contracts for lightning protection, emergency light servicing and dry riser servicing, fire stopping in an electrical room, removal of rubbish from the electrical room, securing of electrical cupboards in the stairwell, compartmentation inspection to service risers and other hatches, replacement of the lift room door, upgrading of the locks to the lift room access door, repair of bin chute hopper, installation of internal signage for the dry risers and fitting of locks to unsecure hatches.</p> <p>A repair order has already been raised on NEC for one flat door, so the job has not been replicated in this report.</p>

London Borough of Hammersmith & Fulham

Guidance

Copyright:

The information contained within this Fire Risk Assessment (FRA) document is owned by the London Borough of Hammersmith & Fulham (LBHF) and may not be used or reproduced without written permission. This document is provided, to the recipient, subject to specific obligations of confidentiality set forth in one or more binding legal agreements between LBHF and the recipient.

Scope of Assessment:

This FRA has been carried out on behalf of the 'Responsible Person' in accordance with Article 9 of the requirements of the Regulatory Reform (Fire Safety) Order 2005 (FSO). The purpose of this report is to provide an assessment of the risk to life from fire in this premise and where appropriate, to identify significant findings to ensure compliance with fire safety legislation as obliged observing current best practice, providing a minimum fire safety standard.

This report reflects the fire safety standards identified during inspection and does not address the risk fire may pose to property or business continuity.

In order to carry out this fire risk assessment the assessor has used their professional expertise, judgement and guidance contained in the British Standards Institute's publicly available specification (PAS 79: 2012), the Department for Communities & Local Government guidance, 'Fire Safety Risk Assessment - Sleeping Accommodation', Local Authorities Coordinators of Regulatory Services (LACORS) 'Housing Fire Safety' guidance and NFCC guidance 'Fire Safety in Specialised Housing'.

Which provides best practice guidance on fire safety provisions in England for certain types of existing housing; as well as the Local Government Association (LGA) Guidance 'Fire safety in purpose-built blocks of flats'.

The aim of the fire risk assessment process is not necessarily to bring an existing building up to the standard expected for a new building, constructed under current legislation. Rather, the intention is to identify measures which are practicable to implement in order to provide a reasonable level of safety for people in and around the premises. Information for the completion of this assessment was obtained by a physical type 1 survey, in compliance with LBHF policy and for the purpose of satisfying the FSO. The inspection of the building is non-destructive. The fire risk assessment will consider the arrangements for means of escape and so forth that will include examination of at least a sample of flat entrance doors. It also considers, so far as reasonably practicable, the separating construction between the flats and the common parts without any opening up of construction; however, in this type of survey, entry to flats beyond the area of the flat entrance door, is not involved as there is normally no automatic right of access for freeholders.

If your premises have been designed and built in line with modern building regulations (and are being used in line with those regulations), your structural fire precautions should be acceptable. While every effort is made to inspect fire compartmentation & fire separating elements of buildings, dependant on accessibility, including roof spaces, voids and service risers, to assess the integrity, comments reflect reasonable assumption. Unless there is reason to expect serious deficiencies in structural fire protection – such as inadequate compartmentation, or poor fire stopping – a type 1 inspection will normally be sufficient. Where doubt exists in relation to these matters, the action plan may recommend that one of the other types of fire risk assessment be carried out or that further investigation be carried out by specialists. (Any such recommendation would be based on identification of issues that justify reason for doubt.)

The FRA includes an Action Plan that sets out measures to enable the Responsible Person to achieve this benchmark risk mitigation level, satisfy the requirements of the FSO and to protect Relevant Persons (as defined in Article 2 of the FSO), from the risks of fire.

London Borough of Hammersmith & Fulham

Compartmentation and Building Features

From a Type 1 inspection perspective, are there breaches identified effecting compartmentation along the escape route?	No
From a Type 1 inspection perspective, are there ineffective or inappropriate materials used to create compartmentation?	N/A
Does the building have a roof void?	Yes
Are there roof void access hatches within the communal areas?	Yes
Are all roof void access hatches fitted with securing devices?	No
Are all hatches providing suitable fire and smoke resistance?	Unable to Confirm
Was a survey of the roof void carried out as part of this inspection?	Yes
Is the compartmentation within the roof void to the correct standard?	Unable to Confirm
Is the roof void clear of personal items or artefacts?	Yes
Are there other concerns identified with the roof void?	No
Are lifts installed?	Yes
Does each lift have a fire service over-ride switch?	Yes
Are there any fire-fighting lifts?	No
Is there a lift motor room?	Yes
Is the compartmentation acceptable?	Yes
Did you get access to survey the lift motor room?	Yes
Are there any other concerns with Lifts or the Lift Motor Room?	Yes
Are there utility cupboards within the communal area?	Yes
Are there any breaches in compartmentation?	Yes
Do utility cupboard doors appear to be FD30s standard?	Yes
Is there evidence to confirm FD30s doors are certified?	No

London Borough of Hammersmith & Fulham

Is there damage to any part of the door or frame affecting its performance as a 30 minute fire and smoke resistant door?	No
Is there personal items or rubbish in any inspected utility or riser cupboard?	Yes
Is there a CO2 extinguisher installed inside any large electrical riser cupboard?	N/A
Are CO2 extinguishers compliant?	N/A
Are there other concerns identified with the utility cupboards and vertical risers?	Yes
Is external cladding fitted to the building?	No
Are the internal escape route walls and ceilings to Class 0 standard?	Yes
Are there other concerns identified with flammable materials?	N/A

Means of Escape

Is the stated emergency evacuation strategy suitable?	Yes
Are fire action notices displayed at the entrances, fire exits and each level as required?	Yes
Are travel distances appropriate for the building design?	Yes
Are the internal escape route corridors free of trip hazards?	Yes
Are stairs free of all trip hazards?	Yes
Are there personal items exceeding the managed policy for communal areas, adversely affecting the escape routes?	No
Do final exits open in the direction of flow where required?	Yes
Are cable and wire fixings to external walls/ceilings to current standards to limit the likelihood of wire entanglement?	Yes
Are there suitable door opening devices such as thumb turns, push pad/bar?	Yes
Is directional and exit signage necessary in this building?	Yes
Are directional and exit signs displayed appropriately?	Yes
Does the building have an external escape route?	No
Are there other concerns identified with the evacuation of the building?	No

London Borough of Hammersmith & Fulham

Is emergency lighting installed?	Yes
Does the installed emergency lighting provide suitable coverage?	Yes
Are there recorded or observable defects with the emergency lighting system?	No
Is there evidence of a current and up-to-date emergency lighting service contract and maintenance programme?	No
If no emergency lighting is installed, does the building require the installation of an emergency lighting system?	N/A
Is there a need to increase the emergency lighting provision?	No
Are there other concerns identified with the emergency lighting?	No
Does the building have suitable means to naturally ventilate the escape routes?	Yes
Is there a smoke ventilation system installed?	No
Are there any concerns identified with ventilation of the internal escape route?	No

London Borough of Hammersmith & Fulham

Doors

Is the main entrance door suitable as part of the evacuation strategy for the building?	Yes
Is security to the property suitable to restrict access to uninvited persons during 'out of hour' times?	No
Are there a sufficient number of fire exits?	Yes
Are there any defects (glazing, furniture, frames, door) requiring repair or maintenance works?	Yes
Do any fire exits lead to areas that could put persons at further risk?	No
Do all fire exits have suitable signage?	Yes
Are there other concerns identified with the main entrance and fire exit doors?	No
Are there any compartment fire doors installed in this building?	No
Is every compartment fire door and frame installed to the correct fire rating standard?	Unable to Confirm
Does every compartment door freely self close into the frame?	Unable to Confirm
Are there any defective compartment fire doors (glazing, furniture, frames, door) requiring repair or maintenance works?	Unable to Confirm
Are there locations where compartment fire doors should be installed?	No
Are there other concerns identified with the compartment fire doors?	N/A
Are there any flat entrance doors not conforming to FD60s standard?	N/A
Do the inspected FD60s doors have certified markings?	N/A
Are positive action self-closers fitted and to the front face of the doors?	Yes
From the sample inspection taken, do the flat entrance doors freely self close into the frame?	Yes
Are there any defective flat entrance doors (glazing, furniture, frames, door) requiring repair or maintenance works?	Yes
Are there other concerns identified with the flat entrance doors?	No

London Borough of Hammersmith & Fulham

Fire Hazards

Are "No Smoking" signs displayed at each entrance?	Yes
Is a no smoking policy being observed in the communal areas?	Yes
Any other concerns identified with smoking?	No
Are there suitable locations provided for storage of refuse?	Yes
Is the refuse area appropriately clear and well managed?	No
Are vertical refuse chutes fitted to the building?	Yes
Are the hoppers in good condition and fitted with smoke seals?	No
Is there a working pull plate at the base of the chute?	Yes
Does the refuse system appear to be free of physical defects?	Yes
Are there other concerns identified with refuse?	Yes
Has fixed electrical wiring been subject to a safety inspection within the past five years?	Yes
Is there a lightning protection system installed?	Yes
Is there evidence of a valid certification?	No
Is the lightning protection free from defects and secured sufficiently?	Yes
Is there a wheelchair or stair lift in the communal area?	No
Are there electrical or charged items in the communal area (fridges, tumble dryers, mobility scooters etc)?	No
Any other concerns identified with ignition sources?	No

London Borough of Hammersmith & Fulham

Fire Detection

From the sample flats accessed, is early warning fire detection appropriate?

Yes

London Borough of Hammersmith & Fulham

Fire Safety Management

Are there hydrants within the grounds of the property estate?	No
Are there notable restrictions for the positioning of fire appliances within 20 metres of the building?	No
Is a Premises Information Box installed?	Yes
Are there complexities or unique features to the building to warrant the installation of a Premises Information Box?	N/A
Is there a working Drop Key mechanism to access the building?	Yes
Is there a Dry Riser installed?	Yes
Are there outlets on each level above the 6th storey?	N/A
Is there evidence to confirm the Dry Riser is serviced?	Unable to Confirm
Is Dry Riser signage displayed appropriately?	No
Are there any observable defects to inlets or outlets and their casings?	Yes
Are there other concerns identified for fire service operations?	No
Did you encounter any potential or actual hoarding risks?	No
LBHF have a medical register of O2 users, did you encounter a resident declaring they were using O2 but not registered?	No
Is there a suppression system installed within any part of the building?	No
Did you encounter any potential hazards due to negligent contractor work at the property and its grounds?	N/A
Are there other concerns identified to do with fire safety management?	No
Does the building contain both commercial outlets and residential dwellings?	No
Any other concerns identified with control of shared means of escape?	N/A

London Borough of Hammersmith & Fulham

Safety Management

Are there staff or site managers based at and working in the building?	No
Are staff trained to support an evacuation of the building during a fire emergency?	N/A
Any other concerns identified with on-site staff and their training?	N/A
Are fire safety records accessible in a suitable physical or digital format for fire inspection audits?	Yes
Is LBHF emergency and general contact details displayed in the communal area?	No
Any other concerns identified with the management of information?	Yes

Actions Arising from the Survey:

	Slight Harm	Moderate Harm	Extreme Harm
Low	Trivial Risk	Tolerable Risk	Moderate Risk
Medium	Tolerable Risk	Moderate Risk	Substantial Risk
High	Moderate Risk	Substantial Risk	Intolerable Risk

Risk Scores:	
Risk Score at the time of the Assessment	Moderate Risk
Risk Score if all actions are implemented:	Tolerable Risk