

London Borough of Hammersmith & Fulham



Fire Risk Assessment of:	Muscal House (9-67) Field Road London W6 8HS
Author of Assessment:	Z Noorgat LBHF Fire Safety Surveyor
Quality Assured by:	Claire Norman, Senior Fire Surveyor, LBH&F
Responsible Person:	Richard Shwe
Risk Assessment Valid From:	03/04/2025
Risk Assessment Valid To:	03/04/2026

London Borough of Hammersmith & Fulham

Building Features

Approximate Square Area of the Building:	500m2
Number of Dwellings:	59
Number of Internal Communal Stairs:	1
Number of External Escape Stairs:	0
Number of Final Exits:	2
Number of Stair Lifts:	
Number of Storeys	12
Uninhabited Roof Void?	
Basement Present?	
Gas Installed to Building?	yes
Solar Panels Installed on Building?	no
Number of Occupants:	118
Current Evacuation Policy:	Stay Put Procedure
Recommended Evacuation Policy:	Stay Put Procedure
Last LFB Inspection:	

London Borough of Hammersmith & Fulham

Survey Findings:

<p>Building Construction & Layout:</p>	<p>A 12-storey building with 59 flats, constructed around 1980 with traditional masonry and reinforced concrete. It features concrete floors, staircases, and a flat roof housing water tanks and the lift motor room. Externally, there are a hopper bin shed, pump room, dry riser inlet, a locked shed, an electricity cupboard, and a water tap in a locked cupboard. The main entrance, accessed via ramp or steps, leads into a lobby with two lifts, fire control systems, distribution boards, electric supply cupboards, and Flats 9 and 10. The lobby connects to a corridor, stairwell, and rear emergency exit. The stairwell, with FD60S fire doors, leads to upper floors with five flats per floor. Each floor has fixed vents, balconies, bin chute rooms, and two corridors. Corridors serve flats, riser cupboards, and AOV vents. Emergency lighting, exit signs, fire notices, and no smoking signs are throughout. The building has an LPS system and fire-rated flat entry doors. Dry risers are on all floors, and the lift motor room is on the roof. A resident car park is on-site, and on-street parking is available. The nearest fire hydrant is at Greyhound Road and Kinnoul Road.</p>
<p>Executive Summary</p>	<p>The assessor was able to gain access to the communal area and the following requires further attention:</p> <ul style="list-style-type: none"> - Cladding window panels within staircase require repair. Also combustible insulation noted within the cladding. - Recommendation for all communal fire doors to be upgraded with FD60S doorsets. - Flat entrance doorset damaged and requires replacement. - Due to the risk profile and height of the building it is recommended to install an evacuation alert system to BS8629 . This system would enable evacuation control by the fire services - Crudely installed and exposed electrical wiring required repair. - Due to age of building and presence of shared ducts a type 4 FRA survey is required. - Obstructions/ combustible items noted in hallway. - It was noted that ducting was passing through between communal lift lobby and flat entrance lobby throughout the block. - Fire stopping required to service void penetrations. - External cladding noted to building

London Borough of Hammersmith & Fulham

Guidance

Copyright:

The information contained within this Fire Risk Assessment (FRA) document is owned by the London Borough of Hammersmith & Fulham (LBHF) and may not be used or reproduced without written permission. This document is provided, to the recipient, subject to specific obligations of confidentiality set forth in one or more binding legal agreements between LBHF and the recipient.

Scope of Assessment:

This FRA has been carried out on behalf of the 'Responsible Person' in accordance with Article 9 of the requirements of the Regulatory Reform (Fire Safety) Order 2005 (FSO). The purpose of this report is to provide an assessment of the risk to life from fire in this premise and where appropriate, to identify significant findings to ensure compliance with fire safety legislation as obliged observing current best practice, providing a minimum fire safety standard.

This report reflects the fire safety standards identified during inspection and does not address the risk fire may pose to property or business continuity.

In order to carry out this fire risk assessment the assessor has used their professional expertise, judgement and guidance contained in the British Standards Institute's publicly available specification (PAS 79: 2012), the Department for Communities & Local Government guidance, 'Fire Safety Risk Assessment - Sleeping Accommodation', Local Authorities Coordinators of Regulatory Services (LACORS) 'Housing Fire Safety' guidance and NFCC guidance 'Fire Safety in Specialised Housing'.

Which provides best practice guidance on fire safety provisions in England for certain types of existing housing; as well as the Local Government Association (LGA) Guidance 'Fire safety in purpose-built blocks of flats'.

The aim of the fire risk assessment process is not necessarily to bring an existing building up to the standard expected for a new building, constructed under current legislation. Rather, the intention is to identify measures which are practicable to implement in order to provide a reasonable level of safety for people in and around the premises. Information for the completion of this assessment was obtained by a physical type 1 survey, in compliance with LBHF policy and for the purpose of satisfying the FSO. The inspection of the building is non-destructive. The fire risk assessment will consider the arrangements for means of escape and so forth that will include examination of at least a sample of flat entrance doors. It also considers, so far as reasonably practicable, the separating construction between the flats and the common parts without any opening up of construction; however, in this type of survey, entry to flats beyond the area of the flat entrance door, is not involved as there is normally no automatic right of access for freeholders.

If your premises have been designed and built in line with modern building regulations (and are being used in line with those regulations), your structural fire precautions should be acceptable. While every effort is made to inspect fire compartmentation & fire separating elements of buildings, dependant on accessibility, including roof spaces, voids and service risers, to assess the integrity, comments reflect reasonable assumption. Unless there is reason to expect serious deficiencies in structural fire protection – such as inadequate compartmentation, or poor fire stopping – a type 1 inspection will normally be sufficient. Where doubt exists in relation to these matters, the action plan may recommend that one of the other types of fire risk assessment be carried out or that further investigation be carried out by specialists. (Any such recommendation would be based on identification of issues that justify reason for doubt.)

The FRA includes an Action Plan that sets out measures to enable the Responsible Person to achieve this benchmark risk mitigation level, satisfy the requirements of the FSO and to protect Relevant Persons (as defined in Article 2 of the FSO), from the risks of fire.

London Borough of Hammersmith & Fulham

Compartmentation and Building Features

From a Type 1 inspection perspective, are there breaches identified effecting compartmentation along the escape route?	Yes
From a Type 1 inspection perspective, are there ineffective or inappropriate materials used to create compartmentation?	No
Does the building have a roof void?	No
Was a survey of the roof void carried out as part of this inspection?	N/A
Are there other concerns identified with roof void?	No
Are lifts installed?	Yes
Does each lift have a fire service over-ride switch?	No
Are there any fire-fighting lifts?	No
Is there a lift motor room?	Yes
Is the compartmentation acceptable?	No
Did you get access to survey the lift motor room?	Yes
Are there any other concerns with Lifts or Lift Motor Room?	No
Are there utility cupboards within the communal area?	Yes
Are there any vertical or horizontal breaches in compartmentation?	Yes
Do utility cupboard doors appear to be FD30s standard?	Yes
Is there evidence to confirm FD30s doors are certified?	No
Is there damage to any part of the door or frame affecting its performance as a 30 minute fire and smoke resistant door?	No
Are there personal items or rubbish in any inspected utility or riser cupboard?	No
Are CO2 extinguishers installed inside each electrical riser?	No
Are CO2 extinguishers compliant?	N/A
Are there other concerns identified with the utility Cupboards and vertical risers?	Yes

London Borough of Hammersmith & Fulham

Is external cladding fitted to the building?	Yes
Does the external cladding appear suitably fitted and in good condition?	Yes
Is the external cladding constructed from fire rated materials?	Unable to Confirm
Are the internal escape route walls and ceilings to Class 0 standard?	Yes
Are there other concerns identified with flammable materials?	Yes

Means of Escape

Are fire action notices displayed at the entrances, fire exits and each level as required?	Yes
Are travel distances appropriate for the building design?	Yes
Are the internal escape route corridors free of trip hazards?	No
Are stairs free of all trip hazards?	Yes
Are there personal items exceeding the managed policy for communal areas, adversely affecting the escape routes?	Yes
Do final exits open in the direction of flow where required?	Yes
Are cable and wire fixings to external walls/ceilings to current standards to limit the likelihood of wire entanglement?	No
Are there suitable door opening devices such as thumb turns, push pad/bar?	Yes
Is directional and exit signage necessary in this building?	Yes
Are directional and exit signage displayed appropriately?	Yes
Where lifts are installed, are suitable fire safety signs displayed at each level?	Yes
Does the building have an external escape route?	No
Are there other concerns identified with the evacuation of the building?	No
Is emergency lighting installed?	Yes
Does the installed emergency lighting provide suitable coverage?	Yes
Are there recorded or observable defects with the emergency lighting system?	No

London Borough of Hammersmith & Fulham

Is there evidence of a current and up-to-date emergency lighting service contract and maintenance programme? Yes

Does the building require the installation of an emergency lighting system?	N/A
---	-----

Is there a need to increase the emergency lighting provision?	N/A
---	-----

Are there other concerns identified with the emergency lighting?	No
--	----

Does the building have suitable means to naturally ventilate the escape routes?	Yes
---	-----

Is there a smoke ventilation system installed?	No
--	----

Are there any concerns identified with ventilation of the internal escape route?	No
--	----

Are all individual flat numbers highlighted using wayfinding signage?	Yes
---	-----

Are all floors on the landing of a protected stairway highlighted using wayfinding signage?	Yes
---	-----

Are all floors on the landing of a protected corridor and lobby highlighted using wayfinding signage?	Yes
---	-----

Are there floor identification floor signs required where the flat numbers are located in more than one direction?	Yes
--	-----

Are there appropriate evacuation signs on each floor within the communal lobbies?	Yes
---	-----

Doors

Is the main entrance door suitable as part of the evacuation strategy for the building?	Yes
---	-----

Is security to the property suitable to restrict access by uninvited persons during 'out of hour' times?	Yes
--	-----

Are there a sufficient number of fire exits?	Yes
--	-----

Are there any defects (glazing, furniture, frames, door) requiring repair or maintenance works?	No
---	----

Do any fire exits lead to areas that could put persons at further risk?	No
---	----

Do all fire exits have suitable signage?	Yes
--	-----

Are there other concerns identified with the main entrance and fire exit doors?	Yes
---	-----

Are there any compartment fire doors installed in this building?	Yes
--	-----

London Borough of Hammersmith & Fulham

Is every compartment fire door and frame installed to the correct fire rating standard?	Yes
Does every compartment door freely self close into the frame?	No
Are there any defective compartment fire doors (glazing, furniture, frames, door) requiring repair or maintenance works?	Yes
Are there locations where compartment fire doors should be installed?	N/A
Are there other concerns identified with the compartment fire doors?	Yes
Are there any flat entrance doors not conforming to FD60s standard?	No
Where FD60s doors have been installed, do any inspected doors not have a certification marking or certificate onsite ?	No
For open deck buildings, are there flat entrance doors not at a suitable fire and security standard?	No
Are positive action self-closers fitted and to the front face of the doors?	Yes
From the sample inspection taken, do the flat entrance doors freely self close into the frame?	Yes
Are there any defective flat entrance doors (glazing, furniture, frames, door) requiring repair or maintenance works?	No
Are there other concerns identified with the flat entrance doors?	No

London Borough of Hammersmith & Fulham

Fire Hazards

Are "No Smoking" signs displayed at each entrance?	Yes
Is a no smoking policy being observed in the communal areas	Yes
Any there other concerns identified with smoking?	Yes
Are there suitable locations provided for storage of refuse?	Yes
Is the refuse area appropriately clear and well managed?	Yes
Are vertical refuse chutes fitted to the building?	Yes
Are the hoppers in good condition and fitted with smoke seals?	Yes
Is there a working pull plate at the base of the chute?	Yes
Does the refuse system appear to be free of physical defects?	Yes
Are there other concerns identified with refuse?	No
Has fixed electrical wiring been subject to a safety inspection within the past five years	Yes
Is there a lightning protection system installed?	Yes
Does the lightning certificate display a valid inspection date?	Yes
Is the lightning Protection free from defects and secured sufficiently?	Yes
Is there a wheelchair or stair lift in the communal area?	No
Are there electrical or charged items in the communal area (fridges, tumble dryers, mobility scooters etc)?	No
Any there other concerns identified with ignition sources?	Yes

London Borough of Hammersmith & Fulham

Fire Detection

From the sample flats accessed, is early warning fire detection appropriate Yes

Fire Safety Management

Are there hydrants within the grounds of the property estate? No

Are there notable restrictions for the positioning of fire appliances within 20 meters of the building? No

Is a Premises Information Box installed? Yes

Are there complexities or unique features to the building to warrant the installation of a Premises Information Box? Yes

Is there a Wet Riser installed? No

Is there a Dry Riser installed? Yes

Are there Dry Riser outlets on each level above the 6th storey? Yes

Is there evidence to confirm Dry Risers are serviced? Yes

Are Dry Riser signs displayed appropriately? Yes

Are there any observable defects to Dry Riser inlets or outlets and their casings? No

Are there other concerns identified for fire service operations? No

Did you encounter any potential or actual hoarding risks? No

LBHF have a medical register of O2 users, did you encounter a resident declaring they were using O2 but not registered? No

Is there a suppression system installed within any part of the building? No

Did you encounter any potential hazards due to negligent contractor work at the property and its grounds? No

Are there other concerns identified to do with fire safety management? No

London Borough of Hammersmith & Fulham

Does the building have both commercial outlets and residential dwellings?	No
Any other concerns identified with the shared means of escape?	No
Is there a secured SIB appropriately and securely located inside or on the exterior of the building?	Yes
Does the SIB have appropriate signage securely fixed to the SIB door?	Yes
Where the SIB is not on view externally, is there appropriate signage internally to assist in locating the SIB?	Yes
Does the SIB contain:	yes
Does the SIB contain:	yes
Does the SIB contain:	yes
Does the SIB contain:	yes
Does the SIB contain:	yes
Does the SIB contain:	yes
Does the SIB contain:	yes
Does the SIB contain:	yes
Does the SIB contain:	yes
Does the SIB contain:	yes
How is access given the Fire and Rescue Service?	Sharing of keys
Has documentation relating to the assessment of the external wall structure been provided prior to the fire risk assessment being undertaken?	No
Where there is evidence of a risk of external spread of fire, has the design of the external wall construction and the materials used been:	yes
Where there is evidence of a risk of external spread of fire, has the design of the external wall construction and the materials used been:	no
Where there is evidence of a risk of external spread of fire, has the design of the external wall construction and the materials used been:	no
Where there is evidence of a risk of external spread of fire, has the design of the external wall construction and the materials used been:	yes

London Borough of Hammersmith & Fulham

Is there evidence that all essential fire-fighting equipment has been visually inspected on a monthly basis?	Yes
Is there evidence that all defects relating to essential fire-fighting equipment has been actioned?	Yes
Have all fire fighting and evacuation lifts been identified?	Yes
Is there evidence of any defective fire-fighting and evacuation lifts which cannot be repaired within 24 hours been reported to the FRS?	No
Is there evidence that all communal fire doors being checked every 3 months?	Yes
Is there evidence that with all best endeavours all in-flat front doors are being checked annually?	Yes

Safety Management

Are there staff or site managers based at and working in the building?	No
Are staff trained to support an evacuation of the building during a fire emergency?	N/A
Are fire safety records accessible (digital or paper) for fire inspection audits?	Yes
Are LBHF emergency contact details displayed?	Yes
Any there other concerns identified with the management of information?	No
Are in-house checks of the Emergency Lighting being carried out and recorded?	Yes
Are in-house checks of the Extinguishing Media being carried out and recorded?	N/A
Are in-house checks of Fire exits and Escape routes being carried out and recorded?	Yes

Actions Arising from the Survey:

London Borough of Hammersmith & Fulham

	Slight Harm	Moderate Harm	Extreme Harm
Low	Trivial Risk	Tolerable Risk	Moderate Risk
Medium	Tolerable Risk	Moderate Risk	Substantial Risk
High	Moderate Risk	Substantial Risk	Intolerable Risk

Risk Scores:	
Risk Score at the time of the Assessment	Moderate Risk
Risk Score if all actions are implemented:	Tolerable Risk