



### ESTATE INSPECTION REPORT (E2) To be circulated within 7 days of the estate inspection

### Name of estate or block Bulow Court

Date of inspection 19/05/22

## Attendees

| Name                        | Contact details  | Representing  |
|-----------------------------|--|---|
| Elizabeth Oliwo-<br>Oyenuga | Elizabeth.oliwo-oyenuga@lbhf.gov.uk  | LBHF  |
| Andrew West                 | Andrew.west@lbhf.gov.uk  | Works Manager-<br>Direct Labour<br>Organisation (DLO) |
| Stephen<br>Nbaluka          | Stephen Mbaluka<br>Stephen.Mbaluka@pinnaclegroup.co.uk                           | Caretaker manager                                     |
| Gittens Leanne              | Gittens Leanne: H&F<br><leanne.gittens@lbhf.gov.uk></leanne.gittens@lbhf.gov.uk> | СМО   |

### Housing management (for example ASB, tenancy condition and concerns)

Responsible officer: Elizabeth Oliwo-Oyenuga Contact details: Elizabeth.oliwo-oyenuga@lbhf.gov.uk

| Action requested | Location of issue | Reference | Target date |
|------------------|-------------------|-----------|-------------|
|                  |                   |           |             |
|                  |                   |           |             |

| Repairs  |                       |            |             |  |
|--|-----------------------|------------|-------------|--|
| Action requested   | Location of issue     | Reference  | Target date |  |
| Make good hole in the<br>ceiling on top floor next<br>to the loft hatch.   | Bulow Court Block 1-7 | 413307 X 1 | 19/7/22     |  |
| Ease and adjust metal<br>bin room located in the<br>front of the building<br>doors that are really<br>stiff.<br>(Bronzewood) | Bulow Court Block 1-7 | 023009 x 2 | 19/7/22     |  |
| Ease and adjust metal<br>bin room located in the<br>front of the building  | Bulow court 13 -18    | 023009 x 2 | 19/7/22     |  |





|  |                            | IIdIIIII   | ersmith & fulham |
|--|----------------------------|------------|------------------|
| doors that are really<br>stiff.<br>(Bronzewood)  |                            |            |                  |
| Ease and adjust metal<br>bin room located in the<br>front of the building<br>doors that are really<br>stiff.<br>(Bronzewood) | Bulow court 19 -24         | 023009 X 2 | 19/7/22          |
| Ease and adjust metal<br>bin room located in the<br>front of the building<br>doors that are really<br>stiff.<br>(Bronzewood) | Bulow Court<br>Block 25-30 | 023009 X 2 | 19/7/22          |
| Refix timber panel in<br>front of the main<br>entrance door  | Bulow court 25-30          | 387017 X 1 | 19/7/22          |
| Ease and adjust metal<br>bin room located in the<br>front of the building<br>doors that are really<br>stiff.<br>(Bronzewood) | Bulow Court<br>Block 31-36 | 023009 X 2 | 19/7/22          |

# Planned or cyclical works

| Action requested | Location of issue | Reference | Target date |
|------------------|-------------------|-----------|-------------|
|                  | N/A               | N/A       | N/A         |

### **Grounds maintenance**

Resident score: No score given as no residents attended the inspection

| Action requested | Location of issue | Reference | Target date |
|------------------|-------------------|-----------|-------------|
|                  | N/A               | N/A       | N/A         |

# Pinnacle caretaking

Resident score: No score given as no residents attended the inspection

| Action requested | Location of issue | Reference | Target date |
|------------------|-------------------|-----------|-------------|
|                  | N/A               | N/A       | N/A         |

# Other (for example street lighting, highways, planning)

| Action requested | Location of issue | Reference | Target date |
|------------------|-------------------|-----------|-------------|
|                  | N/A               | N/A       | N/A         |



Time and date of next inspection 27<sup>th</sup> July 2022

