



### ESTATE INSPECTION REPORT (E2) To be circulated within 7 days of the estate inspection

Name of estate or block Barton House

Date of inspection

31.05.22

### Attendees

Name	Contact details	Representing
Andrew West	Andrew.west@lbhf.gov.uk	Repairs
Stephen Mbaluka	"Stephen.Mbaluka@pinnaclegroup.co.uk"	Caretaker
Michael Balogun	Michael.balogun@lbhf.gov.uk	HM

# Housing management (for example ASB, tenancy condition and concerns)

Responsible officer: Contact details:

Action requested	Location of issue	Reference	Target date
N/A			

#### Repairs

Responsible officer: Contact details:

Action requested	Location of issue	Reference	Target date
Renew 28W bulb to the bulkhead fitting outside flat 53. Resecure the bulkhead fitting shade outside flat 33.	Barton House	857019 x 4 1hr Dayworks to resecure 2no light shades	31.07.22
Renew 28W bulb to the bulkhead fitting on the 5 <sup>th</sup> floor staircase.			
Renew 28W bulb to the bulkhead fitting on the 3 <sup>rd</sup> floor staircase.			
Resecure the bulkhead fitting shade on the 3 <sup>rd</sup> floor landing.			
Renew 28W bulb to the			





## Planned or cyclical works

Responsible officer:

Contact details:

Action requested	Location of issue	Reference	Target date
N/A			

### **Grounds maintenance**

Responsible officer:

Contact details:

Resident score: X out of 5 or No score given as no residents attended the inspection

Action requested	Location of issue	Reference	Target date
N/A			

### **Pinnacle caretaking**

Responsible officer:

Contact details:

Resident score: X out of 5 or No score given as no residents attended the inspection

Action requested	Location of issue	Reference	Target date
N/A			

### Other (for example street lighting, highways, planning)

Responsible officer: Contact details:

Action requested	Location of issue	Reference	Target date
N/A			

### Time and date of next inspection

10am on July 2022 TBC